# Il Cubatore x

### **Quick Start** Digital caliper






#### General use

Il Cubatore is used to digitally measure the volume of logs, with or without bark. Prior to measurement, basic batch data such as customer, wood type, quality and bark content (percentage, etc.) are entered into Il Cubatore application, then the diameter is measured log by log (also in two steps horizontally and vertically) with the digital caliper. Length and quality (or wood type) can be quickly modified with a swipe in Il Cubatore application. The application constantly displays the quantity and total volume with and without bark.

At the end, the measurement data can still be checked, modified or completed, printed with the portable printer or, if a mobile network is available, transferred to Il Cubatore cloud. Il Cubatore cloud is a website where data entered can be managed, measurement lists printed out and data exported to other applications. It is also possible to enter, modify or complete basic data such as customers, wood types, etc.

This Quick-Start manual explains how to perform your first measurement.






#### Smartphone user guide



- 1 Adjust volume
- 2 Switching the smartphone on and off
- 3 Charging the battery

### **Caliper and laser operating instructions**



- Activate laser & confirm measurement
- 2 Deactivating the laser
- 3 Bluetooth connection and battery status
- 4 Batteries
- 5 Foldable
- 6 Adjustable

#### Step #1: Create a new lot

- Switch on the laser
- 4 Create a new lot by pressing the + symbol
- 2 Check Bluetooth connection \*
- 5 Enter the mandatory data and click on the check


- 3 App > Menu > Lots
- 6 You can start measuring!














<sup>\*</sup> The bluetooth symbol on your smartphone must be green. If it's red or for other problems with the connection see below in the section "Questions and answers"



#### Step #2: Measure

- 1 Open the caliper
- Measure logs with the caliper
- 3 Double-click on the laser to perform the measurement
- 4 Complete the lot
- 5 Synchronize data with the cloud



### Il Cubatore ×

#### **Step #3: Cloud-Software**

- 1 Log on to www.infometrics.eu
- 4 Export to Excel


2 Menu > Lots


5 Print files


3 Batch detail view












To export a batch, print it, modify it, delete it, etc., check the box on the right.

#### **Questions and answers**

#### Bluetooth connection caliper > smartphone/application

- 1 Activate laser
- Activate/check Bluetooth on your smartphone
- 3 Open the App on your smartphone
- Click on the bluetooth symbol (red) and select "Disto"
- Check connection on smartphone (symbol must be green) and laser













# II Cubatore



## II Cubatore











www.infometrics.eu +39 0472 057890